

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

MILL CREEK 2 AND 3 HYDROELECTRIC SYSTEMS,
MILL CREEK 3 INTAKE
Mill Creek
Yucaipa vicinity
San Bernardino County
California

HAER No. CA-2272-I

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David G. De Vries, photographer, February-June 2008

CA-2272-I-1	LOOKING EAST TOWARDS MILL CREEK 3 DIVERSION DAM. FROM LEFT: FLOOD DAMAGED COBBLE WALL, BYPASS GATE, AND COBBLE BERM OF DIVERSION DAM.
CA-2272-I-2	VIEW OF THE DIVERSION DAM SHOWING FROM LEFT: LOW CINDERBLOCK RETAINING WALL, BARBED WIRE SECURITY FENCE ABOVE BYPASS GATE, AND CONCRETE WALL ABOVE COBBLE BERM OF THE DIVERSION DAM.
CA-2272-I-3	VIEW FROM ACCESS ROAD TOWARDS INTAKE. FROM LEFT: CINDERBLOCK UTILITY SHED, BYPASS GATE TO SANDBOX, BYPASS GATE TO MILL CREEK BED AND DIVERSION DAM.
CA-2272-I-4	A VIEW TO THE NORTH FROM ATOP THE DIVERSION DAM, SHOWING THE RESERVOIR.
CA-2272-I-5	RESERVOIR, LOOKING WEST.
CA-2272-I-6	LOOKING WEST DOWN MILL CREEK FROM JUST BELOW THE MILL CREEK 3 DIVERSION DAM.
CA-2272-I-7	INTAKE GRILL, ALSO SHOWING FROM LEFT: UTILITY SHED, BYPASS GATE TO SANDBOX, INTAKE GRILL, HISTORIC CONCRETE WALL, AND THE RESERVOIR BEHIND THE WALL.
CA-2272-I-8	SANDBOX BYPASS GATE, FLOW GAUGE, AND WATER LEVEL INDICATOR.
CA-2272-I-9	BYPASS GATE FROM RESERVOIR TO MILL CREEK BED.
CA-2272-I-10	BYPASS GATE AND DIVERSION DAM. FROM LEFT: CINDERBLOCK RETAINING WALL, BYPASS GATE, AND COBBLE BERM OF DIVERSION DAM.

MILL CREEK 2 AND 3 HYDROELECTRIC SYSTEMS,
MILL CREEK 3 INTAKE
HAER No. CA-2272-I
INDEX TO PHOTOGRAPHS
(Page 2)

CA-2272-I-11	ANOTHER VIEW OF THE BYPASS GATE SHOWING THE GATE LEVEL CONTROL WHEEL. VIEW TO EAST.
CA-2272-I-12	DETAIL OF BYPASS GATE GEAR ASSEMBLY, TO SOUTH.

MILL CREEK 2 AND 3 HYDROELECTRIC SYSTEMS,
MILL CREEK 3 INTAKE
HAER No. CA-2272-I
INDEX TO PHOTOGRAPHS
(Page 3)

